



## Heave Load Measurement

---

- **Heave Compensation** - Drill String Tension is constantly measured to ensure that fatigue and force evaluation are monitored and controlled in this intrinsically safe area.



The wedge socket is an application for special load pins. The pins are designed for the application and for the moon pool area it has to be marine resistant.

